

The latest technology for early fault detection

A guide on using vibration sensors to spot the top four pump and motor faults By John Bernet, Fluke Corporation, and Alex Desselle, Fluke Accelix

About vibration monitoring

Continuous condition monitoring is one of the first steps toward predictive maintenance and, ultimately, connected reliability, which gives teams a roadmap for moving past incremental gains to make a quantum leap to an ideal setup. Condition monitoring with vibration sensors allows maintenance teams to obtain baseline data, trend data to detect changes and investigate these changes when abnormalities caused by these faults are found. Vibration sensors can be the eyes on the facility floor, 24 hours per day, seven days each week, even when personnel are attending to other assets or off work.

For top tier, process-critical machines, vibration monitoring is essential. Traditional vibration analysis often involves a vibration expert, which adds expense, and is often only conducted a few times each year. Monitoring mid-tier and bottom-tier assets has not been cost-effective and scalable, until now.

Vibration screening allows teams to be notified of abnormal vibration, receive early warning for further analysis, diagnosis with a spectral analyzer, and perform the right corrective action at the right time. Wireless vibration sensors, such as the Fluke 3561 FC, allow maintenance technicians to spend less time taking manual readings and walking routes and more time addressing problems.

The top five benefits of vibration screening and cloud-based condition monitoring software are:

- 1. Screen quickly, act quickly
- 2. Organize information for data-driven decisions
- 3. Receive alarms when abnormalities occur
- Alarm based on abnormalities caused by the four most common faults (imbalance, misalignment, bearing wear and looseness)
- 5. Reduce maintenance spend

In pumps, motors and most other rotating equipment, the four most common faults are misalignment, looseness, imbalance and bearing wear. All these can cause increased power consumption, vibration and stress on shafts. This article will discuss the causes of these faults and how best to detect and how to use screening to gain early notification of them to avoid asset damage or failure.

The big 4 faults

When rotating assets, including pumps and motors, experience failure, chances are that one of these four failure modes was involved.

1. Misalignment

Without early intervention, misalignment results in worn or failed bearings, and other wear and damage. In worst-case scenarios, misalignment may lead to cracked or broken shafts, which can be personnel safety hazards as well as problems for the asset. Shaft misalignment will also cause vibration that may lead to looseness in many areas in pumps and motors. A misaligned shaft will transmit damaging cyclical forces along the shaft and into the motor, leading to excess wear on the motor and increasing the mechanical load.

Misalignment may be caused by:

- Improper shaft installation
- Foundation or baseplate issues (such as soft foot)
- Faulty or improperly installed bearings
- Improperly coupled pump and motor
- Unbalanced load
- Coupling damage
- Seal or bearing wear



If a pump's impeller is imbalanced, vibration will occur, and the pump's performance and efficiency will be adversely affected, with poor production and excess costs. With time, the imbalance will cause pump failure. If the baseplate or foundation is uneven or if one of the motor's feet is uneven, soft foot can occur, causing excess vibration. In worst-case scenarios, imbalance left unchecked can lead to cracked or broken shafts, which can be personnel safety hazards.



Imbalance may be caused by:

- Eroded impeller blades
- Problems with motor rotors
- Improper bearing installation
- Bent shaft

3. Looseness

The shaft, foundation, or a component may become loose. This causes forces that lead to excessive vibration and increases the wear in the bearings and seals. It may also cause baseplate problems, including soft foot; loose bolts; cracks in a frame; or improper fit between components, including impeller clearances. If not identified and corrected, looseness will shorten the asset's and other components' lives, ultimately causing failure.

Looseness may be caused by:

- Improper installation
- Manufacturing defects
- Baseplate issues
- Improperly torqued fasteners
- Underlying vibration from other faults

4. Bearing wear

Bearing wear is usually caused by other factors acting on the bearings. If the bearings are failing prematurely, the other low-level faults (imbalance, misalignment, or looseness) may be the cause. For example, moderate misalignment may or may not increase in severity over time, but the effects of this misalignment will add to the stress on bearings and seals. Vibration sensors display all the faults found in a machine so that potential candidates for root cause failure may be identified before bearing wear occurs. Even if misalignment is not extreme, it should still be diagnosed and corrected as soon as possible to avoid collateral damage to the asset's bearings and seals.

Other causes of bearing wear are:

- Contamination
- Improper lubrication
- Improper installation
- Improperly torqued fasteners
- Electrical damage

A new and scalable solution

The Fluke 3561 FC is small enough to fit in hardto-reach places and affordable enough to place on multiple locations on equipment (for example, four test points). Precise placement increases accuracy and reduces the time it takes to screen an asset. The data generated from the 3561 FC is wirelessly transmitted and stored using Fluke Connect[™] Condition Monitoring software. The cloudbased software can be downloaded to a smart device or computer, allowing teams to remotely monitor asset health and review historical data anytime and almost anywhere with an Internet connection.

Fluke Connect software even generates automatic alerts when measurements travel outside safe parameters, notifying maintenance team members before issues become critical. With vibration screening, early indications of abnormalities can help teams do the following:

- Avoid unexpected downtime
- Find (with further examination) and fix failures at an earlier stage
- Collect historical data to justify maintenance spend
- Democratize vibration expertise for nonexperts providing easy-to-interpret data
- Screen vibrations on hard-to-access machines
- Collect and analyze cloud-based vibration data

Setup

The triaxial 3561 FC Vibration Sensors are placed on assets throughout the facility, perhaps initially focusing on bad actors to determine the best way to improve their operation. Application is as simple as cleaning the location on which the sensor will be placed and mounting the sensor on the asset with epoxy.

Pumps and motors transmit their vibrations from the shaft to the bearings to the housing and then to the casing. Each sensor should be installed so it is mechanically coupled properly to detect the energy. Avoid locations that may dampen or absorb the vibrations.





Getting started

The Fluke 3561 Vibration Sensor starter kit includes four sensors to collect data, one gateway to send data from the sensors to the cloud, and a 1-year license for Fluke Connect software so you can access the data and receive alarms. The 3561 FC is available through your local distributor with kits starting at \$1,100.



Accelix. Connected Reliability.

Fluke Corporation PO Box 9090, Everett, WA 98206 U.S.A.

For more information call: In the U.S.A. 856-810-2700 In Europe +353 507 9741 In UK +44 117 205 0408 Email: support@accelix.com Web access: http://www.accelix.com

©2018 Fluke Corporation. 8/2018 6011348-en

Modification of this document is not permitted without written permission from Fluke Corporation.